

Grove

GMK4100

11006004

- \*Left front outrigger rail bent
- \*Rust on chrome of boom lift cylinder
- \*Major hyd leak inside right front beam of outrigger
- \*Left front outrigger not holding pressure keep falling down
- \*Major hyd leak valve body upper unit behind cab
- \*Major hyd leak at valve body for right rear outrigger
- \*Upper unit eng. No turnover with starter and hard to bar motor over
- \*Not able to run upper system due to no start
- \*Mirror missing on upper unit right side
- \*Mirror broke at skylight glass
- \*Lower a/c inop
- \*Upper door keeps coming off track
- \*Few lights unop