

Grove

RT530E-2

233933

- *Right front outrigger leaking (mid leak) fails crane
- *Left front outrigger leaking (mid leak) fails crane
- *A/C condenser mounting box is rusted out
- *Needs service/grease, batteries, and turn table needs grease and same with the teeth
- *Boom lift cylinder rust pitting bad on chrome will made cylinder leak
- *A/C not working
- *Outrigger control pressure set to high need turn down
- *COMPUTER SYSTEM NOT WORKING and running on override
- *NO SAFTEY FUNTIONS WORKING A2b, LMI, load charts
- *360 house lock rusted and stuck dose not work
- *BIG RUST pits forming that with out repair soon will cause major structural failure