

Grove

GMK5110-1

51106010

- \*Lower unit driver window inop off track and stuck down
- \*Can't read or see system screen going out on upper unit
- \*Small hyd leak right side between 4<sup>th</sup> and 5<sup>th</sup> axle
- \*Small hyd leak on valve bodys upper unit
- \*Mirror missing on right side upper unit
- \*Lower a/c inop
- \*Upper a/c inop
- \*Door seals driver side and under cab seal came apart and hanging
- \*Few of the lights inop
- \*Codes on lower unit for cable break
- \*Will not auto level as should throws codes at end
- \*Rigging box bent will not close all the way
- \*Climb ladder bent
- \*Becan light missing rear of upper unit